

Langas/Ljungby storm water basin, Falkenberg Sweden, 1998

Basin for balancing storm water fluctuation in agricultural area. Sandy soil condition with great risk for erosion. Slopes covered with THULICA KK-8, coir ECB, seeded and planted.

